

NOTE: THE FLOODPLAIN LIMITS AS SHOWN ARE WITHIN THE ACCURACY OF THE BASE MAPPING. SITE SPECIFIC GROUND ELEVATIONS SHOULD BE CONFIRMED BY FIELD SURVEY. 2. PROBLEMS RELATED TO MAJOR CHANNEL DISLOCATION, PROPERTY DAMAGE AND DEBRIS OR ICE JAMMING HAVE BEEN OBSERVED IN THE BULKLEY RIVER FLOODPLAIN. 3. PONDING MAY OCCUR UPSTREAM OF TRANSPORTATION ROUTE EMBANKMENTS DUE TO DEBRIS JAMMING AT BRIDGES OR CULVERTS RESULTING IN THE FLOOD LEVELS SHOWN TO BE EXCEEDED. Image: 1 . <del>بلہ سے ب</del>ے ر 552.0 551.7 553.0 552.7 551.0 550.7 LIMIT OF STUDY LEGEND ΚΕΥ ΜΑΡ DESIGNATED FLOODPLAIN LIMIT





	CHECKED		BULKLEY RIVER			
	RIVER SURVEY MP		· · · -	QUICK		JSTON
	DESIGNED BB	10	00m 0	100 SC/	200 ALE 1:5000	300
Pedice .	ENGINEER R.W.IV.	J.L.	RECOMMENDED		,	APPROVED